2501/206 TOOL ROOM PROCESSES TECHNOLOGY II AND METROLOGY June/July 2023

Time: 3 hours



THE KENYA NATIONAL EXAMINATIONS COUNCIL

DIPLOMA IN MECHANICAL ENGINEERING (PRODUCTION OPTION)

MODULE II

TOOL ROOM PROCESSES TECHNOLOGY II AND METROLOGY

3 hours

INSTRUCTIONS TO CANDIDATES

You should have the following for this examination:

Answer booklet;

Mathematical tables / Scientific calculator;

Drawing instruments.

This paper consists of EIGHT questions in TWO sections; A and B.

Answer any FIVE questions taking at least TWO questions from each section.

All questions carry equal marks.

Maximum marks for each part of a question are indicated.

Candidates should answer the questions in English.

This paper consists of 5 printed pages.

Candidates should check the question paper to ascertain that all the pages are printed as indicated and that no questions are missing.

SECTION A: TOOL ROOM PROCESSES II

Answer at least TWO questions from this section.

1.	(a)	State:			
		(i)	two advantages of boring over drilling.		
		(ii)	two operations that can be performed on a horizontal boring machine.	(4 marks)	
	(b)	With the aid of a sketch, explain the operation of a table type horizontal borin machine.		g (7 marks)	
	(c)	Illustrate an external surface broaching operation.			
	(d) A 30 mm long piece of mild steel has a bore of ϕ 40.32 mm, which is broached to ϕ 40.82 $^{+0.02}$ mm. Take t = 0.025 mm, K = 5000 N, S=5 at number of cutting teeth = 3. Determine:			nish	
		(i)	the length of the cutting portion of the broach;		
		(ii)	the force required to pull the broach through the work.	(5 marks)	
2.	(a)	(i)	List three reasons for gear finishing operations.		
		(ii)	With the aid of a sketch, describe burnishing as a gear finishing process	ss. (9 marks)	
	(b)	With th	ne aid of sketches, describe gear hobbing as a gear manufacturing meth	od. (11 marks)	
3.	(a)	(i)	State two applications of ultrasonic machining process.		
		(ii)	With the aid of a diagram, explain the operation principle of ultrasonic machine.	(11 marks)	
	(b)		ne aid of a sketch, describe the procedure for milling a constant rise car ag head.	n on a (9 marks)	

1.

State:

- 4. (a) Differentiate between blanking and punching in press tool work. (3 marks)
 - (b) With the aid of a sketch, describe the rack and pinion press drive. (4 marks)
 - (c) (i) Illustrate crater and flank wears on a single point cutting tool.
 - (ii) A tool gave a life span of 3 hours between re-grinds while operating with rough cut on mild steel at 20 m/min. Estimate the life of this tool on similar cuts at a speed of 30 m/min.

 Take $n = \frac{1}{g}$. (8 marks)
 - (d) With the aid of a sketch, explain the internal centreless grinding process. (5 marks)

SECTION B: METROLOGY

Answer at least TWO questions from this section.

5. (a) Explain the role of standards room in a factory.

(3 marks)

- (b) (i) List three precautions to be taken to conserve the accuracy of slip gauges.
 - (ii) Table 1 shows a set of 56 pieces of slip gauges. Outline the procedure for building the slip gauges to give each of the following dimensions:
 - (I) 49,3825 mm;
 - (II) 77.3215 mm.


(9 marks)

Table 1

No.	No. of pieces	Size range	Increment
1	1	1.0005 mm	-
2	9	1.00 - 1.009 mm	0.001 mm
3	9	1.01 - 1.09 mm	0.01 mm
4	9	1.0 - 1.9 mm	0.1 mm
5	25	1 - 25 mm	1.0 mm
6	3	25 - 75 mm	25 mm

- (c) (i) Describe combination bars as used in measurements.
 - (ii) State two applications of combination bars.

(4 marks)



- 6. (a) Explain kinematic principles applied on each of the following:
 - (i) moving jaw of a vernier caliper;
 - (ii) drilling machine spindle.

(4 marks)

- (b) With the aid of a sketch, explain the principle of operation of the Eden-Rolt "millionth' comparator. (11 marks)
- (c) (i) Define statistical quality control.
 - (ii) Differentiate between measurement by attributes and measurement by variables in statistical quality control. (5 marks)
- 7. (a) Explain the BS 3730 requirements on the nature of each of the following, for the determination of departure from roundness:
 - (i) stylus instruments;
 - (ii) stylus for the instruments.

(4 marks)

- (b) Explain each of the following with regard to assessment of roundness errors:
 - (i) Least Square Centre (LSC);
 - (ii) Minimum Zone Centre (MZC).

(4 marks)

- (c) With the aid of a sketch, describe the construction features and the operation of a clinometer. (12 marks)

 (a) Differentiate between each of the following pairs of screw threads elements:

 (i) lead and pitch;

 (ii) major diameter and effective diameter. (4 marks)
 - (b) Describe each of the following screw thread call ups:
 - (i) M18 6g;

8.

- (ii) M28 4h. (4 marks)
- (c) With the aid of sketches, describe the measurement of flank angle of a screw thread, using a microscope. (8 marks)
- (d) Illustrate the set-up for testing a lathe machine bed for level and wind. (4 marks)

THIS IS THE LAST PRINTED PAGE.